======= Software Version TW-LTE Router 2.0.29-17 Released on 20181126 ========

Based on version 2.0.29-16 to add the following changes.

- 1. Added Quectel LTE module support.
- Changed default NTP server to time.google.com
- 3. Updated patch for CVE-2016-10229 secure issue.
- 4. Fixed the issue that EWAN2 can not work when resetting to factory default.

======= Software Version TW-LTE Router 2.0.29-16 Released on 20160408 ========

Based on version 2.0.29-15 to add the following changes.

1. Fixed the bug when EWAN2 set to DHCP mode and has hostname set, EWAN2 can not get IP address correctly.

======= Software Version TW-LTE Router 2.0.29-15 Released on 20160406 ========

Based on version 2.0.29-14 to add the following changes.

- 1. Changed default WiFi key bakc to latest 8 digital of MAC address.
- 2. Changed IPTV QoS setting to disable as default.

======= Software Version TW-LTE Router 2.0.29-14 Released on 20160401 ========

Based on version 2.0.29-11 to add the following changes.

- 1. Fixed the Syslog server setting issue with the case without default value.
- Added htop command for monitoring device.

======= Software Version TW-LTE Router 2.0.29-11 Released on 20160309 ========

Based on version 2.0.29-5 to add the following changes.

- Added Syslog server support on WEB GUI.
- 2. Added Subnet prefix support for QoS Upload/Download rule. The Dest.IP / Src. IP address can support subnet option now.

Example: IP/Prefix number ==> Range of Prefix number is 1~32. Single IP: 100.0.0.1

Subnet: 100.0.0.1/24 ==> Class C

======== Software Version TW-LTE Router 2.0.29-5 Released on 20160120 ========

Based on version 2.0.29-2 to add the following changes.

- 1. Added SMS control function.
- 2. Added the VPN Default Gateway function support, the VPN tunnel can be activated as default route with Remote Access mode.
- 3. Fixed the bug that Virtual Server is not work when the private port set to 80.

4. Fixed the Load Sharing WEB GUI setting issue.

Note: When activate the VPN tunnel as default gateway, please make sure your DNS server can work outside your country.

If not, please set Google DNS server 8.8.8.8 or 9.9.9.9 dns manually.

======== Software Version TW-LTE Router 2.0.29-2 Released on 20151218 =========

Based on version 2.0.29-1 to add the following changes.

1. Fixed the issue that PPTP client can not connect with PureVPN service.

======== Software Version TW-LTE Router 2.0.29-1 Released on 20151209 ========

Based on version 2.0.29 to add the following changes.

1. Change default 3G/4G keep alive value to 60s from 7s.

======= Software Version TW-LTE Router 2.0.29 Released on 20151123 ========

Based on version 2.0.28-8 to add the following changes.

1. Updated WiFi 2.4G driver to vresion 2.7.2.0 to improve WiFi stability.

======== Software Version TW-LTE Router 2.0.28-8 Released on 20151112 ========

Based on version 2.0.28-7 to add the following changes.

- 2. Improved the device security to prevent the XSS hacking command.

======= Software Version TW-LTE Router 2.0.28-7 Released on 20151105 =======

Based on version 2.0.28-6 to add the following changes.

- 1. Removed 8.8.8.8 in default DNS server setting.
- 2. Fixed WEB GUI configuration bug on WAN setting page.
- 3. Fixed the issue that DNS Relay is not work correctly and makes PC can not access Internet with domain name.
- 4. Changed default SSL port to 587(TLS) instead of port 25 for Mail Alert setting page.

======= Software Version TW-LTE Router 2.0.28-6 Released on 20151029 ========

Based on version 2.0.28-3 to add the following changes.

1. Added current used APN name in system log.