

1. Fixed 4TB UI display issue.
2. Fixed Huawei MA5616 DSLAM 17a sync issue.
3. Support EP-06E all band.
  
4. Release final Realtek DSP code for Huawei MA5616 DSLAM 17a sync issue.
5. Support EM12 and CA display in UI.
6. Fixed EM12 with M50U hot plug issue.