

Release Note 11.08.2021

1. Fixed 8202G in 5G-SA display issue.
2. Fixed 8202G in 5G-NSA display issue under speedtest is running.
3. Add new mechanism - LTE only with 5G disable and NR5G with 5G enable.
4. Fixed LM940 display issue.
5. Fixed EM12 band selection miss.
6. Isolated 5 and 2.4 Ghz WPS function